## **IN THE SPECIFICATION**

In the specification, on page 2, in the Brief Description of the Drawings, please insert the following:

-- Figure 4 is a flowchart diagram of the methods of the present invention.--

In the specification, on page 6, after the third paragraph, please insert the following:

--Referring to Figure 4, there is shown the steps of manufacturing the 3D image display body of the invention. In step S1, a retarder film is formed by laminating a TAC film or CAB film and a drawn PVA film. In step S2, the retarder film is laminated onto a transparent support with an adhesive agent interposed. In step S3, transparent resists members are attached in specified portions "a." In step S4, spaces are left between resist members to form spaces "b." In step S5, the resist member side of the assembly is bonded to a display member to form the 3D image display body of the invention.--